
DUTAIASE CANISTER PURGE VALVES


DESIGNED FOR AN OE-QUALITY REPAIR

PRECISION ENGINEERED AND TESTED TO INTEGRATE WITH EVAP SYSTEM



Turalast CANISTER PURGE VALVES


IMPROVES ON LIMITATIONS IN THE OE DESIGN



OE PROBLEM

The plunger assembly cracks, causing an EVAP system leak.

Source: GM Technical Service Bulletin 18029



PV704 / SKU: 474527 (MADE IN THE USA)

THE DURALAST® DIFFERENCE

Improved geometry keeps the plunger in alignment, reducing wear on the seal. The result is a longer-lasting component.



